

YOCO, Inc.
P. O. Box 78
White Plains, N. C. 27031
Phone: (919) 789-5561

RECEIVED
N.C. Dept. NRCD

SEP 05 1989

**Winston-Salem
Regional Office**

August 31, 1989

North Carolina Dept of Natural Resources
and Community Development
8025 North point Blvd., Suite 100
Winston-Salem, NC 27106
Attn: John M. Stewart

Re: Kerosene Tank--Laboratory Results from Soil Samples
Neighbors #3
Hwy 601
Mt. Airy, NC 27030

Dear Mr. Stewart:

On June 28, 1989, we stated testing the 4000 gallon kerosene tank at the above location. We could not get the tank to hold product, so we boarded the test and started to uncover the top of the tank. When we got to the top of the tank, we discovered a wet spot at one of the welds on top of the tank. This is where the tank was leaking.

On June 29, 1989, we pumped out the tank completely. On July 3, 1989, we removed the tank and prepared to install a new one. On July 10, 1989, Mr. Alex McGilvary, from SPATCO Environmental took 2 soil samples where the tank was located. A copy of the results is enclosed.

After the soil samples were taken, we installed a new Stip 3, 10000 gallon tank from Arnold Equipment Company. After the tank was installed and all the piping was complete, we called SPATCO Environmental back on July 17, 1989 to retest our system. There was no problems in the tank checking out to meet standards.

If you have any questions regarding this matter, please contact me at (919) 789-5561.

Sincerely,


Jerry Atkins

JA/dw

Enclosure